زبان تخصصی مهندسی مکانیک

قسمت نهم

(Stress- Strain diagram) نمودار تنش و کرنش (T-۳-

We saw previous Section that the diagram representing the relation between stress and strain in a given material is an important characteristic of the material.

To obtain the stress-strain diagram of a material, one usually conducts a tensile test on a specimen of the material. One type of specimen commonly used is shown.



معنى	كلمه	معنى	کلمه
كشش	tensile	استوانه ای	cylindrical
معمولا	commonly	دقيق	accurate
قسمت- بخش	portion	درجه- وسیله اندازه گیری	gage
ثبت کردن- درج کردن	inscribe	اندازه گیری کردن	measure

The cross-sectional area of the cylindrical central portion of the specimen has been accurately determined and two gage marks have been inscribed on that portion at a distance  $L_0$  from each other. The distance  $L_0$  is known as the gage length of the specimen.

The test specimen is then placed in a testing machine shown above, which is used to apply a centric load P. As the load P increases, the distance L between the two gage marks also increases.



The distance L is measured with a dial gage, and the elongation  $\delta = L - L_0$  is recorded for each value of *P*.

A second dial gage is often used simultaneously (/ sıml'teınıəsli/) to measure and record the change in diameter of the specimen. From each pair of readings P and  $\delta$ , the stress  $\sigma$  is computed by dividing P by the original cross-sectional area  $A_0$  of the specimen, and the strain  $\varepsilon$  by dividing the elongation  $\delta$  by the original distance  $L_0$  between the two gage marks. The stress-strain diagram may then be obtained by plotting  $\varepsilon$  as an abscissa and  $\sigma$  as an ordinate.

Stress-strain diagrams of various materials vary widely, and different tensile tests conducted on the same material may yield different results, depending upon the temperature of the specimen and the speed of loading.

معنى	کلمه	معنى	كلمه
افزايش طول	elongation	ثبت کردن	record
باهم- همزمان	simultaneously	جفت	pair
افقی (محور)	abscissa	عمودی (محور)	ordinate
مختلف-گوناگون	various	تفاوت داشتن	vary
وسيع	wide	دما	temperature



It is possible, however, to distinguish some common characteristics among the stress-strain diagrams of various groups of materials and to divide materials into two broad categories on the basis of these characteristics, namely, the ductile materials and the brittle materials.

Ductile materials, which comprise structural steel, as well as many alloys of other metals, are characterized by their ability to yield at normal temperatures. As the specimen is subjected to an increasing load, its length first increases linearly with the load and at a very slow rate.

معنى	کلمه	معنى	کلمه
تشخيص دادن	distinguish	پهناور- وسيع	broad
دربرداشتن	comprise	آلياژ	alloy
توانايى- قابليت	ability	خطی	linear
آهنگ	rate	اوليه	initial
مستقيم	straight	شيب تند	Steep slope

Thus, the initial portion of the stress-strain diagram is a straight line with a steep slope.

However, after a critical value  $\sigma_{\gamma}$  of the stress has been reached, the specimen undergoes a large deformation with a relatively small increase in the applied load.

This deformation is caused by slippage of the material along oblique surfaces and is due, therefore, primarily to shearing stresses.

As we can note from the stress-strain diagrams of two typical ductile materials shown above, the elongation of the specimen after it has started to yield can be 200 times as large as its deformation before yield.

After a certain maximum value of the load has been reached, the diameter of a portion of the specimen begins to decrease, because of local instability.

This phenomenon is known as necking. After necking has begun, somewhat lower loads are sufficient to keep the specimen elongating further, until it finally ruptures.

We note that rupture occurs along a cone-shaped surface that forms an angle of approximately  $45^{\circ}$  with the original surface of the specimen. This indicates that shear is primarily responsible for the failure of ductile materials, and confirms the fact that, under an axial load, shearing stresses are largest on surfaces forming an angle of  $45^{\circ}$  with the load.

The stress  $\sigma_Y$  at which yield is initiated is called the yield strength of the material, the stress  $\sigma_U$  corresponding to the maximum load applied to the specimen is known as the ultimate strength, and the stress  $\sigma_B$  corresponding to rupture is called the breaking strength.

معنى	كلمه	معنى	كلمه
تحمل كردن	undergo	لغزش – سر خوردن	slippage
مورب- مایل	oblique	مرسوم- معمول	typical
ناپايدارى	instability	گلویی شدن	necking
کافی	sufficient	بيشتر	further
گسیخته شدن- پاره شدن	rupture	رخ دادن	occur
قيف- مخروط	cone	تقريبا	approximately
زاويه	angle	شکست	failure
تاييدكردن	confirm	نهایی	ultimate



Brittle materials, which comprise cast iron, glass, and stone, are characterized by the fact that rupture occurs without any noticeable prior change in the rate of elongation.

Thus, for brittle materials, there is no difference between the ultimate strength and the breaking strength. Also, the strain at the time of rupture is much smaller for brittle than for ductile materials. Note the absence of any necking of the specimen in the case of a brittle material, and observe that rupture occurs along a surface perpendicular to the load.

معنى	کلمه	معنى	کلمه
چدن	cast iron	بدون	without
قابل توجه	noticeable	قبل	prior
عدم وجود- غيبت	absence	عمود	perpendicular
شروع	onset		

We conclude from this observation that normal stresses are primarily responsible for the failure of brittle materials.

In the case of structural steel, the stress remains constant over a large range of values of the strain after the onset of yield. Later the stress must be increased to keep elongating the specimen, until the

maximum value  $\sigma_U$  has been reached. This is due to a property of the material known as strain-hardening.

